## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,110,263 B2 APPLICATION NO. : 10/797753

263 B2 Page 1 of 1

DATED

: September 19, 2006

INVENTOR(S) : He et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Figures 2A & 2B

[Ref no.] 200 should be deleted.

Figure 5

[Ref no.] 560 should be deleted.

Figure 7

[Ref no.] 724 should be deleted.

Column 3

Line 8, "...dielectric 270..." should read --...dielectric layer 270...--. Line 43, "...traces 314..." should read --...signal traces 324 344...--.

Column 4

Line 4, "...the slot width..." should read --...the slot width 434...-. Line 10-11, "...the inner layers..." should read --...the inner layers 570...-.

Column 5

Lines 43-46, "8. ...located alone..." should read --8. ...located along...-.

Column 6

Lines 37, "...the a assembly..." should read --...the assembly...--.

Signed and Sealed this

Fifteenth Day of July, 2008

JON W. DUDAS
Director of the United States Patent and Trademark Office